


Internal Technical Document

Document # ITD-00045, Rev. E
Issue Date November 27, 2012
Printers Affected T1000

T1000 45100954 Ink Manager PCB Connection Diagram



NOTE: Jumpers are required on J6 and J12 on all software versions. J4 and J10 thermistors have been removed on printer serial number T25 and above therefore a jumper will be required at J4 and J10. When installing version 3492 or greater software J4 and J10 thermistors can be removed and jumper installed at both connections.