



T660 USBXpress Drivers

To make sure that the T660 USBXpress drivers are loaded, you will need to check in the System Parameters on Windows XP.



Open the Control Panel in Windows XP. Go to System Properties and open it.



Got to the "Hardware" tab in the System Properties.

Open the "Device Manager"

