


# Ink Transition Board AA90703



J111 through J117: use P9149-A

## Ink Transition Board Connections


Vutek, Inc **CONFIDENTIAL**

Ink Cabinet Wiring Diagram

|                        |                   |
|------------------------|-------------------|
| Author:<br>Dan Grigore | Date:<br>02/16/04 |
|                        |                   |
|                        |                   |
|                        |                   |

|             |  |                |          |
|-------------|--|----------------|----------|
| B           |  | <b>S8038-A</b> | Rev<br>8 |
| PAGE 1 of 2 |  |                |          |

Serial Mux Board AA99810



MUX Board Connections

|                        |                   |                                |  |         |          |
|------------------------|-------------------|--------------------------------|--|---------|----------|
|                        |                   | Vutek, Ink <b>CONFIDENTIAL</b> |  |         |          |
|                        |                   | Ink Cabinet Wiring Diagram     |  |         |          |
| Author:<br>Dan Grigore | Date:<br>02/16/04 | B                              |  | S8038-A | Rev<br>8 |
|                        |                   |                                |  |         |          |
|                        |                   | PAGE 2 of 2                    |  |         |          |